

## M E M O R A N D U M

TO: HARB MEMBERS

FROM: AMY WOLDT JOHNSON

DATE: JUNE 15, 2021

SUBJECT: JUNE 15, 2021 MEETING AGENDA

The scheduled meeting of the Reading Historical Architectural Review Board will be held on Tuesday, June 15, 2021 at <u>6:30p.m.</u> in City Hall using a virtual meeting application of which will be recorded and posted on the City's Website.

Due to the COVID-19 Emergency Declaration, the public is prohibited from attending the regular HARB meetings. Public comment for the HARB meetings will only be accepted in writing through an email to <a href="mailto:amy.johnson@readingpa.gov">amy.johnson@readingpa.gov</a>. All public comment must be submitted by 5:00pm on the day of the meeting to allow the distribution of the comment submitted to HARB members prior to the start of the meeting. The comment received will be read into the record at the Regular Meeting.

#### **AGENDA**

**6:30 p.m.** Call to order. Reading of the minutes of previous meetings.

6:35 p.m. ITEM #1 921 N. 3rd St.

Norberto Ortiz, Owner

**Composite Index Rating: 104** 

Review proposal for the replacement of the original double wood entrance doors with a single wood and ¾ leaded glass lite door at the first floor front facade; installation of ceramic tile at the first floor front porch (violation – work has been completed).

6:50 p.m. ITEM #2 501 Walnut St. (AKA 209 N. 5th St.)

The Senior Apartments at the Wyomissing Club, Owner

**Composite Index Rating: 82** 

Review request for the replacement of the existing double sided ground mounted sign at the southwest corner of the



property with a 3'-7" x 3'-7" double sided ground mounted sign, mounted on 4" aluminum posts, to read "The SENIOR APARTMENTS AT THE WYOMISSING CLUB, A Community of Phoebe Ministries, 501 WALNUT STREET, PHOEBE MINISTRIES ADMINISTRATION OFFICES", with logo, in black and white letters on a black and white background.

### 7:05 p.m. ITEM #3

#### 401 Penn St.

# Alvernia University, Owner Composite Index Rating: N/A

Review proposal for the installation of 2' diameter x 4" deep internally illuminated sign to depict the Starbucks logo in "Holly Green" on a white background on the interior of the first floor storefront window at the southwestern corner of the building; installation of one 4' diameter x 6-3/8" deep internally illuminated projecting sign to depict the Starbucks logo in "Holly Green" on a white background to be mounted on the second brick pier in from the southwest corner on the Penn Street façade.

### 7:20 p.m. ITEM #4

#### 57 S. 6th St.

# 57 Franklin St. Real Prop LLC, Owner Composite Index Rating: 38

Review proposal for the replacement of existing wood shake shingles with brown asphalt architectural shingles at the first floor roof overhang (violation – work has been completed).

#### 7:35 p.m. ITEM #5

Review applications approved by Staff:

- a. 600 Centre Ave., Steve and Ann Hearing, Owners Painting of exterior wood trim in kind.
- b. 833 Centre Ave., Beth Sullivan, Owner Painting of exterior wood surfaces in kind.
- c. 434 Oley St., Robert Fletcher, Owner Painting of exterior wood surfaces in kind.
- d. 436 Oley St., Robert Fletcher, Owner Painting of exterior wood surfaces in kind.
- e. 438 Oley St., Beth Sullivan, Owner Painting of exterior wood surfaces in kind.

#### 7:40 p.m. Other Business

- Preservation Officer's Report on Action Items:
  - 108 S. 6<sup>th</sup> St. Vinyl window installed incorrectly in the bay window at the southern façade. Staff has sent a compliance letter.
  - 253 N. 5<sup>th</sup> St. Demolition by Neglect, Property Maintenance Violation. The City Codes Office has installed black painted plywood in the window openings to help protect the building. Plans for interior renovations were approved by the Building and Trades Office on December 10, 2015.
  - 34 N. 11<sup>th</sup> St. Standing seam roof approved by HARB but has ridges. Staff to investigate whether what was installed was approved by the HARB.
  - 306 S. 5<sup>th</sup> St. City Council denied the owner's appeal on November 24<sup>th</sup> and the restoration of the front façade was to be completed within 180 days from Nov. 24, 2014 as per Council Res. No. 127-2014. Work has not been completed to date. Staff sent a compliance letter. As of 2017 there is a new owner. Staff has contacted a representative of the new owner regarding the ongoing violation.
  - 927 N. 4<sup>th</sup> St. A temporary repair of the original terra cotta tiled roof was approved by the HARB for 100 days remains in place. Staff is to contact the roofing contractor to determine status.
  - 941 N. 4<sup>th</sup> St. The original cedar shake shingles on the bay window were to be replaced in kind but instead were replaced with 3" vinyl siding in a cypress color which was not approved by the HARB. Staff is to send a violation letter.
  - 407 S. 6<sup>th</sup> St. Work was not completed to HARB specifications. The Board concurred that the undertaken work may be approved if slightly modified. Staff is to discuss the removal of the installed medallions below the storefront window with the contractor.
  - 412 Windsor St. Front entrance door remains in violation. Owner has submitted a proposed door that is appropriate. Staff is to work with owner to obtain compliance.

- 837 Rose St. Entrance steps constructed in violation, work has not been completed as per HARB Res. No. 74-15. Staff sent a compliance letter but to date there has been no response. There is a new owner of the building. Staff is to send a new compliance letter.
- 21 S. 5<sup>th</sup> St. The 90 day extension period for the temporary plywood covering of the dormer windows has expired and the plywood remains. This building has a new owner as of 2020.
- 547 Bingaman St. The HARB approved a half lite wood entrance door to replace the door installed in violation. The existing door has not been installed in compliance with HARB Resolution 25-16. Staff is to send a compliance letter.
- 200 N. 5<sup>th</sup> St. The green marble trim below the storefront window on the southern façade has been altered inappropriately and is not compliant with Resolution 91-14. HARB Discussed ongoing violations at the October 17, 2017 HARB meeting and has given the owner 6 months to present a proposal to address the violation and other proposed work. Staff met with the property owner on March 9<sup>th</sup> to discuss the replacement of windows and proposed repairs as per HARB Resolution No. 67-17. Staff has been in contact with the representative of the building in August 2018 regarding the revised Window Policy.
- 821 N. 5<sup>th</sup> St. Replacement of wood windows on the front façade with aluminum clad wood windows and the installation of vinyl windows on the southern façade were completed in violation and denied. The owner has not replaced the windows according to HARB Res. No. 67-16. Staff is to send a compliance letter.
- o 737 Madison Ave. Modifications to the first floor front porch to install a vertical platform lift were not completed according to HARB Res. No. 03-17. Staff spoke with the representative of the owner regarding the work as completed. The representative of the owner stated that he will look into the matter and will discuss the work with the contractor.
- 1023 N. 5<sup>th</sup> St. Replacement of existing wood lattice at the first floor front porch has not been completed as

- per HARB Res. No. 23-17. Staff is to investigate and send a compliance letter.
- 422 Douglass St. A black wrought iron door has was installed in violation at the basement level entrance at the eastern façade and was denied by the HARB as per Res. No. 18-17. Staff has sent a compliance letter and the owner has replied requesting to be able to appeal the HARB's decision. The appeal period is over and Staff is working with the owner to rectify the matter.
- 914 Madison Ave. The rear fence installed in violation has not been modified as per HARB Res. 30-17. Staff is to send a compliance letter.
- 551 Penn St. The internally illuminated individually lettered sign installed in violation at the storefront has not been removed as per HARB Res. No. 29-17. Staff is to send a compliance letter.
- 53 S. 6<sup>th</sup> St. Signage has not been modified as per HARB Resolution No. 82-17 as made on 12/19/17. Staff has sent a compliance letter.
- 321 N. 5<sup>th</sup> St. The lower portion of the front façade was painted in violation and remains painted. Staff will investigate whether or not they are in compliance with Res. No. 09-18.
- 817 N. 4<sup>th</sup> St. Several proposed alterations have not been completed according to HARB Resolution 08-18. In March 2021, Staff worked with a local roofing contractor and the representative of the owner to make sure they are compliant with Res. No. 08-18 regarding the restoration of wood trim and roofing and the work will be approved at Staff level. As of May 2021 Staff continues to work with a representative of the owner regarding other outstanding issues.
- 647 Bingaman St. Staff is to investigate the installation of the first floor front window.
- 513 S. 5<sup>th</sup> St. Front entrance door was not replaced as per the resolution (elective work) and was painted in a color that was not approved. Staff is to investigate.
- 1164 Perkiomen Ave. The paint color scheme denied by the HARB in HARB Res. No. 14-19 remains at the first floor storefront. Staff is working with the owner and tenant to determine appropriate paint colors for the building and new paint color samples have been submitted.

- 1334 Good St. All of the work has not been completed as per Resolution No. 29-19. The owner was to return with a request for Financial Hardship for various items that are in violation. Staff is to send a compliance letter.
- 354 Penn St. Approved signage was installed as per HARB Resolution No. 38-19 however additional signage may have been installed on the eastern façade. Staff made a site visit in May 2020 and found additional signage had been installed on the eastern façade that was not approved by the HARB. Staff is to contact the business owner.
- 1049 N. 5<sup>th</sup> St. The entrance door installed in violation has been replaced with historically appropriate double entrance doors as per HARB Resolution No. 32-19.
  Painting of the doors requires review. The railing at the first floor front porch installed in violation remains in violation. Staff is to send a compliance letter.
- o 331 Greenwich St. Staff met with the owner on 4/6/21 to discuss proposed work to a rear porch and determined that HARB Res. No. 51-19 has not been complied with the tile installed on the first floor front porch has not been removed. The owner informed Staff that due to COVID, they do not have the funds to bring the porch into compliance but are working on rectifying the issue. Staff attended a court hearing for the property on 5/20/21. The owner has been ordered to begin making necessary improvements to the property (both for the installed tile and other items) and to return to court once a month to show their progress.
- 146 S. 5<sup>th</sup> St. The review of the front entrance steps was tabled (HARB Res. No. 58-19) but the applicant has not proceeded with researching the appropriate material for the partially completed entrance steps. Staff is to reach out to the applicant.
- 1114 Perkiomen Ave. HARB Res. No. 56-19 was appealed to City Council on 2/5/20, the appeal (City Council Res. No. 40-2020) was not adopted and therefore the owner remains in violation of HARB Res. No. 56-19. Staff is to send a compliance letter.
- Staff reported on the December 2020 HARB Resolutions at the May 2021 meeting. January 2021 HARB

resolutions will be reviewed at the June 2021 HARB meeting.

- Education and Outreach Committee Report.
- Policy Committee Report.
- Preservation Commendations.

## 8:00 p.m. Adjournment

H:\CDPlan\COMMDEV\Planning Office Files\Amy\HARB\Harb Agenda June 15, 2021.doc